

1/29

Attorney Case No: 10B-135 USA 000




FIG 1

(Prior Art)

2/29




FIG 2

3/29




FIG. 3A

00000000000000000000




FIG. 3B

5/29




FIG. 4A

6/29




FIG. 4B

7/29




FIG. 5

8/29




FIG. 6

9/29




FIG. 7A

10/29




FIG. 7B

卷之三




FIG. 8

12/29




FIG. 9

(3/29)




FIG. 10

14/29




FIG. 11

15/29




FIG. 12A

16/29




FIG. 12B




FIG. 13

18/29




FIG. 14

19/29




FIG. 15

20/29





FIG. 16

21/29



22/29




FIG. 17B

卷之三





FIG. 18

24/29

2023 RELEASE UNDER E.O. 14176



Fourth Illustrative Embodiment

FIG. 19

Cash Register
+
Customer Receipt Terminal

25/29




FIG. 20

26/29




FIG. 21

27/29




FIG. 22A

28/29




FIG. 22B

卷之三




FIG. 23